SIKKA MALL OF EXPRESSWAY Progress Report for- 17/02/25 To 24/02/25 Mall Photo **Mall Name** Work Done i.e. Back side Elevation MS cantilever-485 sq.ft Mall of Expressway **Mall Name** Work Done i.e. **Mall Photo** RMC-Ground floor column casting work - 14 cum concrete) Mall of Expressway

Mall Name	Mall Photo	Work Done i.e.
Mall of Expressway		2 nd floor wall Dismentling work
Mall Name	Mall Photo	Work Done i.e.
Mall of Expressway		Basement old work fire fight work going on

Mall Name	Mall Photo	Work Done ie.
Mall of Expressway		Cleaning work in going on at 2nd floor
Mall objects	Mall Diagram	Wash Daniela
Mall photo Mall of Expressway	Mall Photo	Work Done i.e. 2nd floor Balcony casting 30 cum concrete