








Sikka Kaamya Project**Progress Report for the period 10-02-2025 to 16-02-2025**

Tower Name	Tower Photo	Item	Progress of work
DIAMOND		RMC/Steel	9th floor roof slab - 100% casted
		Paint	Internal paint to start this week
		Tiling	1st floor completed
		Plumbing	1st floor completed
		Electrical	Yet to start
		M.S. Railings	Yet to start
		Internal Plaster	4th floor in progress
		External Plaster	N/A
		Fire Fighting	Yet to start
RUBY		RMC	Structure Work Completed
		Paint	Intenal putty work completed, external primer done 60%
		Tiling	Wall Tiling at 20th floor in progress
		Plumbing	Internal water supply and drainage work completed
		Electrical	Conduit work completed, wiring work yet to start
		M.S. Railings	Balcony railing completed and staircase railing in progress
		Internal Plaster	Completed
		External Plaster	82% completed
OPAL		RMC	Structure Work Completed
		Paint	Intenal putty work completed, external primer done 55%
		Tiling	Floor Tiling at 16th floor in progress
		Plumbing	Internal water supply and drainage work completed
		Electrical	Conduit work completed, wiring work yet to start
		M.S. Railings	Balcony railing completed and staircase railing in progress
		Internal Plaster	Completed

		<table border="1"> <tbody> <tr> <td>External Plaster</td> <td>82% completed</td> </tr> <tr> <td>Fire Fighting</td> <td>Internal sprinkler system piping completed</td> </tr> </tbody> </table>	External Plaster	82% completed	Fire Fighting	Internal sprinkler system piping completed														
External Plaster	82% completed																			
Fire Fighting	Internal sprinkler system piping completed																			
JADE		<table border="1"> <tbody> <tr> <td>Brickwork / RMC</td> <td>Lift shaft brickwork in progress</td> </tr> <tr> <td>Paint</td> <td>Internal putty work completed, external primer done 50%</td> </tr> <tr> <td>Tiling</td> <td>Tiling at 17th floor in progress</td> </tr> <tr> <td>Plumbing</td> <td>Internal water supply and drainage work completed</td> </tr> <tr> <td>Electrical</td> <td>Conduit work completed, wiring work yet to start</td> </tr> <tr> <td>M.S. Railings</td> <td>Balcony railing completed and staircase railing in progress</td> </tr> <tr> <td>Internal Plaster</td> <td>Completed -90%</td> </tr> <tr> <td>External Plaster</td> <td>75% completed</td> </tr> <tr> <td>Fire Fighting</td> <td>Internal sprinkler system piping in progress</td> </tr> </tbody> </table>	Brickwork / RMC	Lift shaft brickwork in progress	Paint	Internal putty work completed, external primer done 50%	Tiling	Tiling at 17th floor in progress	Plumbing	Internal water supply and drainage work completed	Electrical	Conduit work completed, wiring work yet to start	M.S. Railings	Balcony railing completed and staircase railing in progress	Internal Plaster	Completed -90%	External Plaster	75% completed	Fire Fighting	Internal sprinkler system piping in progress
Brickwork / RMC	Lift shaft brickwork in progress																			
Paint	Internal putty work completed, external primer done 50%																			
Tiling	Tiling at 17th floor in progress																			
Plumbing	Internal water supply and drainage work completed																			
Electrical	Conduit work completed, wiring work yet to start																			
M.S. Railings	Balcony railing completed and staircase railing in progress																			
Internal Plaster	Completed -90%																			
External Plaster	75% completed																			
Fire Fighting	Internal sprinkler system piping in progress																			
AMBER		<table border="1"> <tbody> <tr> <td></td> <td>Structure Work Completed</td> </tr> <tr> <td>Paint</td> <td>Internal putty work completed, external primer done 62%</td> </tr> <tr> <td>Tiling</td> <td>Tiling at 20th floor in progress</td> </tr> <tr> <td>Plumbing</td> <td>Internal water supply and drainage work completed</td> </tr> <tr> <td>Electrical</td> <td>Conduit work completed, wiring work yet to start</td> </tr> <tr> <td>M.S. Railings</td> <td>Balcony railing completed and staircase railing in progress</td> </tr> <tr> <td>Internal Plaster</td> <td>Lift lobby internal plaster - 21st floor</td> </tr> <tr> <td>External Plaster</td> <td>85% completed</td> </tr> <tr> <td>Fire Fighting</td> <td>Internal sprinkler system piping completed</td> </tr> </tbody> </table>		Structure Work Completed	Paint	Internal putty work completed, external primer done 62%	Tiling	Tiling at 20th floor in progress	Plumbing	Internal water supply and drainage work completed	Electrical	Conduit work completed, wiring work yet to start	M.S. Railings	Balcony railing completed and staircase railing in progress	Internal Plaster	Lift lobby internal plaster - 21st floor	External Plaster	85% completed	Fire Fighting	Internal sprinkler system piping completed
	Structure Work Completed																			
Paint	Internal putty work completed, external primer done 62%																			
Tiling	Tiling at 20th floor in progress																			
Plumbing	Internal water supply and drainage work completed																			
Electrical	Conduit work completed, wiring work yet to start																			
M.S. Railings	Balcony railing completed and staircase railing in progress																			
Internal Plaster	Lift lobby internal plaster - 21st floor																			
External Plaster	85% completed																			
Fire Fighting	Internal sprinkler system piping completed																			
SAPPHIRE		<table border="1"> <tbody> <tr> <td>RMC</td> <td>Structure Work Completed</td> </tr> <tr> <td>Paint</td> <td>Internal putty work completed, external painting done 80%</td> </tr> <tr> <td>Tiling</td> <td>Lift Wall Tile Cladding at 11th floor in progress - 50 % completed</td> </tr> <tr> <td>Plumbing</td> <td>Completed</td> </tr> <tr> <td>Electrical</td> <td>Conduit work completed, wiring work in progress</td> </tr> <tr> <td>M.S. Railings</td> <td>Completed</td> </tr> <tr> <td>Internal Plaster</td> <td>Completed</td> </tr> <tr> <td>External Plaster</td> <td>Completed</td> </tr> </tbody> </table>	RMC	Structure Work Completed	Paint	Internal putty work completed, external painting done 80%	Tiling	Lift Wall Tile Cladding at 11th floor in progress - 50 % completed	Plumbing	Completed	Electrical	Conduit work completed, wiring work in progress	M.S. Railings	Completed	Internal Plaster	Completed	External Plaster	Completed		
RMC	Structure Work Completed																			
Paint	Internal putty work completed, external painting done 80%																			
Tiling	Lift Wall Tile Cladding at 11th floor in progress - 50 % completed																			
Plumbing	Completed																			
Electrical	Conduit work completed, wiring work in progress																			
M.S. Railings	Completed																			
Internal Plaster	Completed																			
External Plaster	Completed																			

		Fire Fighting	Completed
--	---	---------------	-----------

PEARL		RMC	Structure Work Completed
		Paint	Completed, final coat balance
		Tiling	Completed
		Plumbing	Completed
		Electrical	Completed
		M.S. Railings	Completed
		Internal Plaster	Completed
		External Plaster	Completed
		Fire Fighting	Completed
EMERALD		RMC/Steel	3rd floor roof R/F work completed, ready for casting
		Paint	Yet to start
		Tiling	Yet to start
		Plumbing	Yet to start
		Electrical	Yet to start
		M.S. Railings	Yet to start
		Internal Plaster	Yet to start
		External Plaster	N/A
		Fire Fighting	Yet to start