Sikka Kaamya Project

Progress Report for the period 20-01-2025 to 26-01-2025

Tower Name	Tower Photo	Item	Progress of work
DIAMOND		RMC/Steel	8th floor roof R/F work in progress
		Paint	Yet to start
		Tiling	1st floor completed
		Plumbing	1st floor completed
		Electrical	Yet to start
		M.S. Railings	Yet to start
		Internal Plaster	1st floor completed
		External Plaster	N/A
		Fire Fighting	Yet to start
RUBY		RMC	Structure Work Completed
		Paint	Intenal putty work completed, external primer done 60%
		Tiling	Tiling at 17th floor in progress
		Plumbing	Internal water supply and drainage work completed
		Electrical	Conduit work completed, wiring work yet to start
		M.S. Railings	Balcony railing completed and staircase railing in progress
		Internal Plaster	Completed
		External Plaster	75% completed
	The same of the sa	Fire Fighting	Internal sprinkler system piping completed
		RMC	Structure Work Completed
OPAL		Paint	Intenal putty work completed, external primer done 55%
		Tiling	Tiling at 16th floor in progress
		Plumbing	Internal water supply and drainage work completed
		Electrical	Conduit work completed, wiring work yet to start
		M.S. Railings	Balcony railing completed and staircase railing in progress
		Internal Plaster	Completed

		External Plaster	68% completed
		Fire Fighting	Internal sprinkler system piping completed
JADE		RMC	Structure Work Completed
		Paint	Intenal putty work completed, external primer done 50%
		Tiling	Tiling at 17th floor in progress
		Plumbing	Internal water supply and drainage work completed
		Electrical	Conduit work completed, wiring work yet to start
		M.S. Railings	Balcony railing completed and staircase railing in progress
		Internal Plaster	Completed
		External Plaster	65% completed
		Fire Fighting	Internal sprinkler system piping completed
		RMC	Structure Work Completed
AMBER		Paint	Intenal putty work completed, external primer done 55%
		Tiling	Tiling at 20th floor in progress
		Plumbing	Internal water supply and drainage work completed
		Electrical	Conduit work completed, wiring work yet to start
		M.S. Railings	Balcony railing completed and staircase railing in progress
		Internal Plaster	Completed
		External Plaster	80% completed
	TANGETHER PRESENTATION OF THE PROPERTY OF THE	Fire Fighting	Internal sprinkler system piping completed
SAPPHIRE		RMC	Structure Work Completed
		Paint	Intenal putty work completed, external painting done 80%
		Tiling	Completed
		Plumbing	Completed
		Electrical	Conduit work completed, wiring work in progress
		M.S. Railings	Completed
		Internal Plaster	Completed
	m : He : W	External Plaster	Completed



Fire Fighting | Completed

PEARL		RMC	Structure Work Completed
		Paint	Completed
		Tiling	Completed
		Plumbing	Completed
		Electrical	Completed
		M.S. Railings	Completed
		Internal Plaster	Completed
		External Plaster	Completed
		Fire Fighting	Completed
EMERALD		RMC/Steel	3rd floor roof R/F work in progress
		Paint	Yet to start
		Tiling	Yet to start
		Plumbing	Yet to start
		Electrical	Yet to start
		M.S. Railings	Yet to start
		Internal Plaster	Yet to start
		External Plaster	N/A
		Fire Fighting	Yet to start