

Sikka Kimaantra Greens

Progress Report For 04.02.25 to 10.02.25

Tower	Photo	Work Done i.e.
	 A photograph showing three construction workers in orange safety vests and yellow hard hats working on a paved area. They are surrounded by large stacks of grey cobblestones. The workers are actively placing the stones onto a prepared base. In the background, there is a blue fence and some trees.	Coble Fixing work
	 A photograph showing two construction workers in orange safety vests and yellow hard hats working on a construction site. They are standing next to a large concrete bucket, mixing mortar. There are several bags of cement and a pile of red bricks nearby. In the background, there are multi-story apartment buildings under construction.	



NTA

Any Other Work





W/P

Tower Name

Tower Photo

Work Done i.e.





Club

Any Other Work







Tower Name

Tower Photo

Work Done i.e.



Electrical Wark



Villa



Any Other Work



Tower Name

Tower Photo

Work Done i.e.



Tiling

Tower 01 02



Cleaning