


Sikka Kimaantra Greens

Progress Report For 14.01.25 to 20.01.25

Tower	Photo	Work Done i.e.
	 A photograph showing two construction workers on a site. One worker, wearing a yellow hard hat and a red safety vest over a brown sari, is using a shovel to spread a large pile of dark grey gravel. Another worker, also in a red safety vest and a dark sari, stands nearby. In the background, there are stacks of grey tiles and a building under construction covered in green safety netting. The ground is wet and reflective.	RMC
	 A photograph of a construction worker wearing a yellow hard hat and a red safety vest. The worker is bent over, using a blue power tool to work on a concrete curb. The curb is painted with yellow and green sections. In the background, there is a concrete floor with a long metal drainage grate.	



NTA

Any Other Work





Electrical

Tower Name

Tower Photo

Work Done i.e.





Club

Any Other Work





Tower Name

Tower Photo

Work Done i.e.



Tower .03

Paint



Painting

Tower Name

Tower Photo

Work Done i.e.



Painting



Block Work