







## ***SIKKA MALL OF EXPRESSWAY***

**Progress Report for- 09/03/25 To 17/03/25**

Mall Name	Mall Photo	Work Done i.e.
<b>Mall of Expressway</b>		Ground floor pop work-700 Sft
Mall Name	Mall Photo	Work Done i.e.
<b>Mall of Expressway</b>		RMC-
		Ground floor column casting work - 12 cum concrete)

Mall Name	Mall Photo	Work Done i.e.
<p style="text-align: center;"><b>Mall of Expressway</b></p>		Basement retaining wall shuttering work in going on
Mall Name	Mall Photo	Work Done i.e.
<p style="text-align: center;"><b>Mall of Expressway</b></p>		3 <sup>rd</sup> floor Outer wall Dismantling work going on

Mall Name	Mall Photo	Work Done i.e.
<p style="text-align: center;"><b>Mall of Expressway</b></p>		<p>Cleaning work in going on at 3<sup>rd</sup> floor</p>
<p><b>Mall photo</b></p>	<p><b>Mall Photo</b></p>	<p><b>Work Done i.e.</b></p>
<p style="text-align: center;"><b>Mall of Expressway</b></p>		<p>Basement retaining wall casting m25-9 cum</p>