SIKKA MALL OF EXPRESSWAY				
Progress Report for- 13/01/25 To 20/01/25				
Mall Name Mall of Expressway	Mall Photo	Work Done i.e. Back side Elevation MS cantilever-560 sq.ft		
Mall Name	Mall Photo	Work Done i.e.		
Mall of Expressway	<image/>	RMC- G. floor column casting work -8 column(6.68 cum micro concrete)		

Mall Name	Mall Photo	Work Done i.e.
Mall of Expressway	<image/>	1st floor Toilet work Dismentling
Mall Name	Mall Photo	Work Done i.e.
Mall of Expressway	<image/>	4th Floor conduit work 187 mtr

Mall Name	Mall Photo	Work Done ie.
Mall of Expressway	<image/>	Cleaning work in going on at G.floor
Mall photo Mall of Expressway	<section-header></section-header>	Work Done i.e. Old work fire fighting Dismentling Ground floor 100 R.ft

-