




Tower Name	PHOTOS	Work Done i.e	Remarks
RETAIL AREA		Fire work	Sprinkler fixing work on 3rd floor Retail area
		Plumbing work	Testing on 3rd floor toilet
		Fire Fighting work	10th floor office tower

		<p><b>Malwa Cleaning</b></p>	<p><b>Malwa Cleaning 100 bags</b></p>
<p><b>Office Tower</b></p>		<p><b>Cut out</b></p>	<p><b>Office tower staircase cut 15 nos</b></p>
		<p><b>Toilet Plumbing work</b></p>	<p><b>03 floor toilet work</b></p>

<b>Non-Tower</b>		<b>Electrical Work</b>	<b>Ceiling conduit 180 Rmt</b>
		<b>Steel Binding</b>	<b>Steel Binding 3 MT</b>